

Modifying the Vivanco AV Control 5

The small board on the front has been removed; therefore two pins on the connector had to be connected.

